**A Quick Guide on fixing9504 LT Key issues**

First of all we need to go into Regedit

Windows XP users, click Start → Run → Type **regedit** → Press Enter

Windows Vista/7 Users, click start, type **regedit** into the little search box.


Then click on **regedit**

Inside regedit, navigate to **HKEY_CURRENT_USER**

Find the folder named **JungleFlasher**

Select it

In the right hand window, you'll see a list of registry entries,

Right click in this area, Click New, **String Value**

Rename **writekey** and press Enter

Then, Right click the new string value → modify data, set value as 1.


Close Regedit

Load JungleFlasher

Load Your dummy.bin / Lite-OFW.bin

When prompted to Autoload, click **Yes**, this will auto load and auto spoof 9504 LT.

Right click inside the circled area and select **WriteKey**

JungleFlasher will then write the correct key to the drive.